

Skyddsron

Showing rooms currently having issues **AND** only from floor areas (rooms) all

Index by org. unit

<p>ALE BioNut 7349 7378 </p> <p>ARI BioNut 8033 8130 8160 </p> <p>Adm BioNut 8817 8820 </p> <p>Adm/Ek BioNut 8816 </p> <p>Adm/IT BioNut 8813 </p> <p>Adm/Utö BioNut 6011 </p> <p>Archive and registry 2313 </p> <p>BEA BioNut 6530 6536 6554 6637 </p> <p>BioNut BioNut 6031 6033 6152 6155 6156 6157 6160 6341 6378 6380 6382 6550 6555 6634 6635 6638 7353 7376 7380 7635 8155 8158 8554 8839 </p> <p>CRI BioNut 6510 6512 </p> <p>ETR BioNut 6316 6346 </p> <p>FA 5001 5310 </p> <p>FACS MedH 7130a </p> <p>FPI BioNut 6134 </p> <p>FoT Clintec 7840 </p> <p>HERM MedH 7032 7033 7120 7134 7138 7152 7155 7156 7160 7353 7378 7821 8021 8150 8152 </p> <p>Hemsö 5408 </p> <p>ICMC MedH 7320 7631 </p> <p>INA BioNut 6346 7378 8820 </p> <p>ITA 3515 3517 3518 </p> <p>ITA Helpdesk 6620 6810 </p> <p>JJO BioNut 8032 8034 8036 8123 8134 </p> <p>JKE BioNut 6510 </p> <p>KEK BioNut 6510 6512 6552 </p>	<p>LA BioNut 6346 </p> <p>LCI BioNut 7362 7840 </p> <p>LJO BioNut 6321 6337 6339 6361 6362 </p> <p>Lipidlab MedH 7353 7535 7552 7554 7555 7635 </p> <p>MBÄ Meds 8034 8160 8554 </p> <p>MER BioNut 6134 </p> <p>MGE BioNut 6560 </p> <p>MLÖ BioNut 6011 </p> <p>NVS-Neo NVS 6382 6552 7819 7830 8020 8034 8036 8138 8150 8152 8158 8160 </p> <p>Neo Service MedH 8620 8835 8836 8837 </p> <p>Neo common 2810 3306 3307 3314 3317 3318 6308 6318 6323 6331 7039 7383 7556 8039 8121 8360 8374 8378 8557 8560 8634 </p> <p>NoGrp 7372 8341 8353 8382 8637 </p> <p>Nordberg NVS 8375 </p> <p>PAN BioNut 7112 7372 7376 7552 </p> <p>PST Clintec 8160 8331 8554 </p> <p>PSV BioNut 7349 7378 </p> <p>PSW BioNut 6512 </p> <p>RST BioNut 8349 8351 8354 </p> <p>SICOF MedH 6374 7331 7333 7631 </p> <p>SOK BioNut 7552 </p> <p>SST BioNut 6321 </p> <p>not_KI 2305 2307 2311 </p> <p>unkBN BioNut 8820 </p>
--	---

Safety inspection (skyddsron) in room 2303

Type of room: Corridor | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
1004 - Fire & Safty equipment - Other - 2021-12-15	A300 - Fix, repair, or install needed - 2021-12-17 A300: First aid kit needs refilling	

Safety inspection (skyddsron) in room 2305

Type of room: Electron Microscopy | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
1009 - Sign & Labels - Other - 2021-04-01 x674 - Evacuation alarm not audible - 2022-12-01 x902 - Missing warning/information signs/pictograms - 2021-04-01	A404 - Put up a sign - 2020-11-04 A404: No warning outside for low ox A404: Unclear what the warning light indicates	

Safety inspection (skyddsron) in room 2307

Type of room: Electron Microscopy | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x674 - Evacuation alarm not audible - 2022-12-01		

Safety inspection (skyddsron) in room 2311

Type of room: Electron Microscopy, Lab | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x104 - Gas cartridges/tanks NOT stored in fire proof cabinet - 2021-04-01 x104: Gas: etan 10 l x602 - Eye shower - 2022-12-01 x602/x611: not signed x611 - Not regularly inspected - 2022-12-01 x602/x611: not signed x8 - Many cardboard/styrofoam boxes in the room - 2022-12-01 x902 - Missing warning/information signs/pictograms - 2021-04-01 x902/A404: unclear what the signs and warning lights indicates x902/A404: No warning in corridor about low ox inside EM rooms or between EM rooms	A404 - Put up a sign - 2020-11-04 x902/A404: unclear what the signs and warning lights indicates x902/A404: No warning in corridor about low ox inside EM rooms or between EM rooms	

Safety inspection (skyddsron) in room 2313

Type of room: Archive | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x10 - Box(es) on the floor - 2022-12-01 x10: många flyttlådor men det ingår i det normala arbetet, så svårt att göra något åt x106 - Evacuation routes (partly) blocked - 2022-12-01 x106: varuvagnar står placerade så att utrymningsvägen mot 2303 blir svårtillgänglig		

Safety inspection (skyddsron) in room 3306

Type of room: LIN filling | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x602 - Eye shower - 2021-12-15	A998 - Request for repair/fix has been sent - 2022-12-08 A998: Order: 802677 2022-12-08 13:38:55	Non specific 2021-12-15 - Low pressure in eye shower 2021-12-15 - Low ox need calibration

Safety inspection (skyddsron) in room 3307

Type of room: Gas Storage | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments

1009 - Sign & Labels - Other - 2021-04-01
x660 - Low oxygen alarm - 2021-04-01

A404 - Put up a sign - 2021-04-01

Non specific
2021-04-01 - Clarification

Safety inspection (skyddsron) in room 3308

Type of room: Corridor | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
1004 - Fire & Safty equipment - Other - 2021-04-01	A330 - Install - 2021-06-15	Non specific 2021-04-01 - Flash light at evacuation station is missing. This is an open area so a replacement will probably be stolen

Safety inspection (skyddsron) in room 3314

Type of room: Contiguous Waste | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x902 - Missing warning/information signs/pictograms - 2021-04-01	A413 - Sign 'BIOLOGISK RISK' needed - 2021-05-03	

Safety inspection (skyddsron) in room 3317

Type of room: Goods reception | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x675 - Evacuation sign missing/malfunctioning - 2022-09-01 x675: Typ av fel : Skylden lyser inte x675: Felbeskrivning : Utrymningsskylt i 3317 saknas	A300 - Fix, repair, or install needed - 2022-09-01	Non specific 2022-09-02 - Order: 770713 Det saknas en utrymningsskylt i rum 3317 ("uppackningsrum") och verkar aldrig ha funnits någon. Det finns ingen utrymningsskylt i hela rummet (tekniskt två rum) över huvud taget.

Safety inspection (skyddsron) in room 3318

Type of room: Freezer hotel | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x106 - Evacuation routes (partly) blocked - 2022-12-01 x106/x4: lots of racks close to the door to 3302 x4 - Many things on the floor/in the room - 2022-12-01 x106/x4: lots of racks close to the door to 3302		

Safety inspection (skyddsron) in room 3515

Type of room: Tech Room Server Hall Batteri | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x674 - Evacuation alarm not audible - 2022-12-01 x674: The building fire alarm is probably not connected to this very noisy room		

Safety inspection (skyddsron) in room 3517

Type of room: Tech Room Server Hall UPS | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x674 - Evacuation alarm not audible - 2022-12-01 x674: The building fire alarm is probably not connected to this very noisy room		

Safety inspection (skyddsron) in room 3518

Type of room: Server Hall | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x674 - Evacuation alarm not audible - 2022-12-01 x674: The building fire alarm is probably not connected to this very noisy room		

Safety inspection (skyddsron) in room 5001

Type of room: Lunch room Mitochondrion | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
1004 - Fire & Safty equipment - Other - 2021-12-15 1007 - Other Risks - 2021-12-15	A300 - Fix, repair, or install needed - 2021-12-17	Non specific <u>2022-12-01 - The Delta repeater is now installed</u> <u>2021-12-15 - Button still sharp</u> <u>2021-12-15 - No first aid kit</u>

Safety inspection (skyddsron) in room 5310

Type of room: Bengt Winblad | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x108 - Hand disinfectant - 2022-12-01 x109 - Surface disinfectant - 2022-12-01	A218 - Reduce the amount - 2022-12-01	

Safety inspection (skyddsron) in room 5408

Type of room: Corridor outside WC | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x106 - Evacuation routes (partly) blocked - 2022-12-01 x106: varuvagnar		

Safety inspection (skyddsron) in room 6011

Type of room: Office | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x108 - Hand disinfectant - 2022-11-30		

Safety inspection (skyddsron) in room 6031

Type of room: Lab Equipment Room | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x903 - Incorrect warning signs/pictograms - 2022-12-01 x903: water in ethanol sq bottle, use correct bottle		

Safety inspection (skyddsron) in room 6032

Type of room: Lab Equipment Room Previous issues fixed: No update this room		
Issues w comments	Actions w comments	Comments
x8 - Many cardboard/styrofoam boxes in the room - 2021-06-15	A200 - Move to other location - 2021-06-15	

Safety inspection (skyddsron) in room 6033

Type of room: Lab Equipment Room | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x12 - Moving boxes - 2021-12-14	A200 - Move to other location - 2022-12-02 A202 - Unpack - 2021-12-17	

Safety inspection (skyddsron) in room 6034

Type of room: Storage | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x676 - Sprinkler need a clearance around it > 30cm - 2022-12-01		

Safety inspection (skyddsron) in room 6036

Type of room: Lab Equipment Room | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x1 - Untidy/messy - 2022-12-01 x10 - Box(es) on the floor - 2021-12-14 x111 - Many ethanol sq. bottles - 2022-12-01 x15 - Boxes/storage on top of fridge/freezers - 2022-12-01 x3 - Insufficient storage - 2021-12-14	A502 - Floor shelves needed - 2021-12-14	

Safety inspection (skyddsron) in room 6039

Type of room: Chemical Storage | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x902 - Missing warning/information signs/pictograms - 2021-06-15	A400 - Use proper Signs and/or labels - 2021-06-15	Non specific 2021-06-15 - Check if the issues and actions are correct

Safety inspection (skyddsron) in room 6101

Type of room: Office Corridor | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x11 - Heavy objects stored high - 2022-11-30 x11: Monitor on top of shelves		

Safety inspection (skyddsron) in room 6117

Type of room: Lab Office | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x108 - Hand disinfectant - 2022-11-30		

Safety inspection (skyddsron) in room 6120

Type of room: Lab Office | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x132 - Electric heater - may blow fuses - 2022-11-30 x134 - Electric kettle not allowed - may blow fuses - 2022-11-30		

Safety inspection (skyddsron) in room 6130N

Type of room: Lab | Previous issues fixed: **Yes** | [update this room](#)

Issues w comments	Actions w comments	Comments
x1 - Untidy/messy - 2022-11-30 x1: lot of stuff on the floor x15 - Boxes/storage on top of fridge/freezers - 2022-11-30 x5 - To many objects in the room - 2021-12-14 x800 - Waste handling/storing not correct - 2022-11-30 x800: Plastic waste in yellow bin - better to use the plastic bags provided for recycling plastic x902 - Missing warning/information signs/pictograms - 2021-12-14	A104 - Shelf above fridges needed - 2022-11-30 A502 - Floor shelves needed - 2021-12-14	

Safety inspection (skyddsron) in room 6130S

Type of room: Lab | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x1 - Untidy/messy - 2022-11-30 x1: lots of yellow bins x101 - To much flammable in the lab - 2021-12-14 x101: many ethanol sq bottles x110 - Flammables incorectly stored - 2022-11-30 x110/x801: flammable waste in fume hood and on the floor under the fume hood x5 - To many objects in the room - 2022-11-30 x5: fridge badly placed x8 - Many cardboard/styrofoam boxes in the room - 2021-12-14 x801 - Improper storage of hazardous waste - 2022-11-30 x110/x801: flammable waste in fume hood and on the floor under the fume hood x902 - Missing warning/information signs/pictograms - 2022-11-30 x902: waste without label - correct marking	A201 - Move or remove - 2021-12-17 A599 - Store it properly - 2021-12-17	

Safety inspection (skyddsron) in room 6134

Type of room: Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x8 - Many cardboard/styrofoam boxes in the room - 2022-12-05 x8: many styrofoam and cardboard boxes and other waste on a trolley in the corridor - bring to recycling room before piles of waste		

Safety inspection (skyddsron) in room 6134N

Type of room: Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x11 - Heavy objects stored high - 2022-12-01 x11: monitor on boxes on top shelf - may belong to Jose Inzunza <jose.inzunza@ki.se> x8 - Many cardboard/styrofoam boxes in the room - 2022-12-01 x8: lots of styrofoam - move excess to the recycling room		

Safety inspection (skyddsron) in room 6138N

Type of room: Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x8 - Many cardboard/styrofoam boxes in the room - 2022-12-01		

Safety inspection (skyddsron) in room 6152

Type of room: Cell Lab Air Lock | Previous issues fixed: **Yes** | [update this room](#)

Issues w comments	Actions w comments	Comments
x900 - Missing routines - 2021-12-14 x900/A603: expired hypochlorite is still useful - use twice amount to make sure the final concentration is > 1%. See Decontamination using sodium hypochlorite, https://staff.ki.se/media/125335/download x900/A603: To much hypochlorite stored, may not be active when used	A603 - Routines has to be updated/changed - 2021-12-17 x900/A603: expired hypochlorite is still useful - use twice amount to make sure the final concentration is > 1%. See Decontamination using sodium hypochlorite, https://staff.ki.se/media/125335/download x900/A603: To much hypochlorite stored, may not be active when used	

Safety inspection (skyddsron) in room 6155

Type of room: Cell Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x111 - Many ethanol sq. bottles - 2022-12-01		

Safety inspection (skyddsron) in room 6156

Type of room: Cold Room | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x7 - Card board boxes in cold room - 2021-12-14	A201 - Move or remove - 2020-11-04 A208 - Move to plastic boxes - 2022-12-01	Non specific <u>2021-12-14 - Sonication</u> <u>2021-03-31 - Risk for mold, Move content to plastic boxes</u>

Safety inspection (skyddsron) in room 6157

Type of room: Storage | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x1 - Untidy/messy - 2022-12-01 x10 - Box(es) on the floor - 2022-12-01		

Safety inspection (skyddsron) in room 6160

Type of room: Lab Equipment Room | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x3 - Insufficient storage - 2021-12-17	A502 - Floor shelves needed - 2021-12-14	

Safety inspection (skyddsron) in room 6161

Type of room: Lab Equipment Room | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x108 - Hand disinfectant - 2022-12-01 x3 - Insufficient storage - 2021-12-14	A502 - Floor shelves needed - 2021-12-14	

Safety inspection (skyddsron) in room 6301

Type of room: Corridor | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x10 - Box(es) on the floor - 2022-11-30 x10: scanner in a box on the floor		

Safety inspection (skyddsron) in room 6308

Type of room: Lab Corridor | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x106 - Evacuation routes (partly) blocked - 2022-05-17 x8/x106/A220: pictures, cardboard and styrofoam in corridor x8 - Many cardboard/styrofoam boxes in the room - 2022-05-17 x8/x106/A220: pictures, cardboard and styrofoam in corridor	A220 - Remove - 2022-05-17 x8/x106/A220: pictures, cardboard and styrofoam in corridor	

Safety inspection (skyddsron) in room 6316

Type of room: Lab Office | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x108 - Hand disinfectant - 2022-11-30		

Safety inspection (skyddsron) in room 6318

Type of room: Silent Room | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x130 - Not allowed equipment - 2022-11-30 x130: electric scooter should be parked in the bicycle garage in Novum		

Safety inspection (skyddsron) in room 6321

Type of room: Lab Office | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x108 - Hand disinfectant - 2022-11-30		

Safety inspection (skyddsron) in room 6323

Type of room: Meeting room Glucose | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x108 - Hand disinfectant - 2022-11-30		

Safety inspection (skyddsron) in room 6331

Type of room: Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x602 - Eye shower - 2022-12-01 x602/A603: not signed - probably not flushed. The fire monitor should do it regularly (or anyone in the lab)	A603 - Routines has to be updated/changed - 2022-12-01 x602/A603: not signed - probably not flushed. The fire monitor should do it regularly (or anyone in the lab)	

Safety inspection (skyddsron) in room 6337

Type of room: Xray Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x1 - Untidy/messy - 2022-12-01 x111 - Many ethanol sq. bottles - 2022-12-01 x8 - Many cardboard/styrofoam boxes in the room - 2022-12-01		

Safety inspection (skyddsron) in room 6339

Type of room: Xray Lab | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x1 - Untidy/messy - 2022-12-01 x3 - Insufficient storage - 2021-05-31	A103 - Shelves - 80 deep needed - 2021-03-31	

Safety inspection (skyddsron) in room 6341

Type of room: Cold Room | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x7 - Card board boxes in cold room - 2021-12-14	A208 - Move to plastic boxes - 2021-05-03	Non specific <u>2021-12-14 - Still there</u>

Safety inspection (skyddsron) in room 6342N

Type of room: Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x15 - Boxes/storage on top of fridge/freezers - 2022-12-01	A104 - Shelf above fridges needed - 2022-12-01	

Safety inspection (skyddsron) in room 6342S

Type of room: Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x1 - Untidy/messy - 2022-12-01 x4 - Many things on the floor/in the room - 2022-12-01 x4: boxes and jerricans x8 - Many cardboard/styrofoam boxes in the room - 2022-12-01		

Safety inspection (skyddsron) in room 6346

Type of room: Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-05-17 x101/x103/A206: Flammables on bench		

Safety inspection (skyddsron) in room 6346N

Type of room: Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x15 - Boxes/storage on top of fridge/freezers - 2022-11-30	A104 - Shelf above fridges needed - 2022-11-30	

Safety inspection (skyddsron) in room 6346S

Type of room: Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x110 - Flammables incorectly stored - 2022-11-30 x110/x801: Flammable waste in fume hood, lots of waste jerrican on the floor x801 - Improper storage of hazardous waste - 2022-11-30 x110/x801: Flammable waste in fume hood, lots of waste jerrican on the floor	A200 - Move to other location - 2022-11-30	

Safety inspection (skyddsron) in room 6361

Type of room: Cell Lab | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x10 - Box(es) on the floor - 2022-12-01 x101 - To much flammable in the lab - 2022-05-17 X101/x103: Flammables on bench - many bottles x103 - Flammable in non-fire proof cabinet - 2022-05-17 X101/x103: Flammables on bench - many bottles	A200 - Move to other location - 2021-12-20 A599 - Store it properly - 2021-12-20	

Safety inspection (skyddsron) in room 6362

Type of room: Cell Lab Air Lock | Previous issues fixed: **Not checked** | [update this room](#)

Issues w comments	Actions w comments	Comments
x602 - Eye shower - 2022-06-28 x602/A603: not signed, probably not flushed, fire monitor or anyone should do it regularly x8 - Many cardboard/styrofoam boxes in the room - 2022-12-01	A200 - Move to other location - 2022-05-17 A603 - Routines has to be updated/changed - 2022-12-01 x602/A603: not signed, probably not flushed, fire monitor or anyone should do it regularly	Non specific <u>2022-06-28 - Blocked by cardboard boxes.</u> <u>2022-06-28 - Kontrollpunkt : Ögonskölj</u> <u>2022-06-28 - Kontaktperson : Sara Söderqvist</u> <u>2022-06-28 - E-post : sara.soderqvist@ki.se</u> <u>2022-06-28 - Typ av fel : Ögonsköljen är blockerad</u> <u>2022-05-17 - X101/x103: Flammables on bench - many bottles</u>

Safety inspection (skyddsron) in room 6364N

Type of room: Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x15 - Boxes/storage on top of fridge/freezers - 2022-12-01	A104 - Shelf above fridges needed - 2022-12-01	

Safety inspection (skyddsron) in room 6374

Type of room: Lab Equipment Room | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-11-30 x101: ethanol x3 - Insufficient storage - 2021-12-17	A502 - Floor shelves needed - 2021-12-14	

Safety inspection (skyddsron) in room 6378

Type of room: Lab Equipment Room | Previous issues fixed: **Yes** | [update this room](#)

Issues w comments	Actions w comments	Comments
x8 - Many cardboard/styrofoam boxes in the room - 2022-11-30		

Safety inspection (skyddsron) in room 6380

Type of room: Lab Equipment Room | Previous issues fixed: **Yes** | [update this room](#)

Issues w comments	Actions w comments	Comments
x340 - Electrical risks - 2022-11-30 x340: Many PCR on same fuse - it may blow if to many on at the same time	A502 - Floor shelves needed - 2021-12-14	Non specific <u>2021-12-14 - Still overflow yellow box</u>

Safety inspection (skyddsron) in room 6382

Type of room: Lab Equipment Room | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-11-30 x101: Ethanol x351 - Malfunctioning door - 2022-11-30 x351: door opener leaking oil x806 - Yellow boxes filled to much (can't be closed) - 2022-11-30 x902 - Missing warning/information signs/pictograms - 2021-12-14 x902: sonicator	A340 - Order the repair/install/fix - 2022-11-30 A502 - Floor shelves needed - 2021-12-14	

Safety inspection (skyddsron) in room 6402

Type of room: Lab Area Corridor at stair SE | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x351 - Malfunctioning door - 2022-06-27		Non specific <u>2022-06-27 - Kontrollpunkt : Branddörr</u> <u>2022-06-27 - Kontaktperson : Sara Söderqvist</u> <u>2022-06-27 - E-post : sara.sodervist@ki.se</u> <u>2022-06-27 - Typ av fel : Dörren går att trycka upp</u> <u>2022-06-27 - Felbeskrivning : Mellan rum 6510 och brandtrappa på sidan av byggnaden. Dörr 6502</u>

Safety inspection (skyddsron) in room 6508

Type of room: Lab Corridor | Previous issues fixed: **Yes** | [update this room](#)

Issues w comments	Actions w comments	Comments
x602 - Eye shower - 2022-06-27 x602/x611: should be flushed regularly by fire monitor or anyone x611 - Not regularly inspected - 2022-12-01 x602/x611: should be flushed regularly by fire monitor or anyone		Non specific <u>2022-06-27 - Ögonsköljen är blockerad . Eye rinse is blocked</u>

Safety inspection (skyddsron) in room 6510

Type of room: Lab Office | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x108 - Hand disinfectant - 2022-11-30		

Safety inspection (skyddsron) in room 6512

Type of room: Lab Office | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x108 - Hand disinfectant - 2022-11-30		

Safety inspection (skyddsron) in room 6530

Type of room: BEA Lab | Previous issues fixed: **Yes** | [update this room](#)

Issues w comments	Actions w comments	Comments
x8 - Many cardboard/styrofoam boxes in the room - 2021-05-31	A340 - Order the repair/install/fix - 2021-05-31	Non specific <u>2021-05-31 - Heating equipment should have a timer</u>

Safety inspection (skyddsron) in room 6536

Type of room: BEA Lab | Previous issues fixed: **Yes** | [update this room](#)

Issues w comments	Actions w comments	Comments
x3 - Insufficient storage - 2021-05-31	A502 - Floor shelves needed - 2022-05-17	

Safety inspection (skyddsron) in room 6538N

Type of room: Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x111 - Many ethanol sq. bottles - 2022-12-01		

Safety inspection (skyddsron) in room 6550

Type of room: Lab Equipment Room | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x702 - Temp to hot - 2022-12-01		

Safety inspection (skyddsron) in room 6552

Type of room: Lab Equipment Room | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x10 - Box(es) on the floor - 2022-12-01 X10: box with burners, pick up by Johan or Håkan?		

Safety inspection (skyddsron) in room 6554

Type of room: Lab Equipment Room | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2021-12-14 x111 - Many ethanol sq, bottles - 2022-12-01	A200 - Move to other location - 2021-12-20	

Safety inspection (skyddsron) in room 6555

Type of room: Dark Room | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x903 - Incorrect warning signs/pictograms - 2022-12-02 x903/x906: unclear in notes - check again x906 - Missing pictograms on chemical cupboard - 2022-12-02 x903/x906: unclear in notes - check again		Non specific 2022-12-08 - phosphorecent indicator at the light switch has been installed

Safety inspection (skyddsron) in room 6558

Type of room: Cell Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x1 - Untidy/messy - 2022-12-05 x1/x10: boxes and jerricans on the floor x10 - Box(es) on the floor - 2022-12-05 x1/x10: boxes and jerricans on the floor		

Safety inspection (skyddsron) in room 6560

Type of room: Cell Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x111 - Many ethanol sq, bottles - 2022-12-01		

Safety inspection (skyddsron) in room 6620

Type of room: Office | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x108 - Hand disinfectant - 2022-11-30 x109 - Surface disinfectant - 2022-11-30		

Safety inspection (skyddsron) in room 6634

Type of room: Chemical Storage | Previous issues fixed: **Not checked** | [update this room](#)

Issues w comments	Actions w comments	Comments
1006 - Lab Risks - Other - 2021-03-31 1006/A401: Unknown samples in fireproof cabinet x903 - Incorrect warning signs/pictograms - 2022-11-30 x903: old pictograms on chemicals x906 - Missing pictograms on chemical cupboard - 2022-11-30	A401 - Label it correctly - 2021-03-31 1006/A401: Unknown samples in fireproof cabinet	

Safety inspection (skyddsron) in room 6635

Type of room: Lab Equipment Room | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x111 - Many ethanol sq, bottles - 2022-12-01		

Safety inspection (skyddsron) in room 6637

Type of room: Lab Equipment Room | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x111 - Many ethanol sq, bottles - 2022-12-01 x902 - Missing warning/information signs/pictograms - 2022-12-01	A417 - Sign 'NO CLEANING' needed - 2022-12-01	

Safety inspection (skyddsron) in room 6638

Type of room: Storage | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x676 - Sprinkler need a clearance around it > 30cm - 2022-12-01		

Safety inspection (skyddsron) in room 6702

Type of room: Office Corridor | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
1009 - Sign & Labels - Other - 2022-08-23	A403 - Replace it with correct sign - 2022-08-23	Non specific 2022-08-23 - Typ av fel : Felplacerad/felvänd 2022-08-23 - Felbeskrivning : Enligt utrymningsplan är "du" 4-5 meter till vänster om där du faktiskt står och läser utrymningsplanen. Enligt planen sitter den, och släckare på väggen mot toaletterna (6708), men i verkligheten är den på väggen bredvid rum 6666. 2022-08-23 - Utrymningsplanen visar även att ögonduch ska finnas, men jag kan inte se någon.

Safety inspection (skyddsron) in room 6810

Type of room: ITA Storage | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x707 - General lighting - 2022-12-02 x707: lights constant on		

Safety inspection (skydds rond) in room 7032

Type of room: Lab Equipment Room | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2021-03-30	A200 - Move to other location - 2021-03-30	Non specific 2021-03-30 - 3 bottles EtOH

Safety inspection (skydds rond) in room 7033

Type of room: Lab Equipment Room | Previous issues fixed: **Not checked** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-05-17 x101/x103: Flammables on bench x11 - Heavy objects stored high - 2020-01-01 x3 - Insufficient storage - 2020-01-01	A502 - Floor shelves needed - 2021-03-30	

Safety inspection (skydds rond) in room 7039

Type of room: Chemical Storage | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x902 - Missing warning/information signs/pictograms - 2022-11-30 x902: not specified in notes		

Safety inspection (skydds rond) in room 7112

Type of room: Office | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x133 - Coffee maker without timer - 2022-11-23		

Safety inspection (skydds rond) in room 7120

Type of room: Lab Office | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x109 - Surface disinfectant - 2022-11-30 x133 - Coffee maker without timer - 2022-11-23		

Safety inspection (skydds rond) in room 7130a

Type of room: Lab (north part of FACS facility) | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x674 - Evacuation alarm not audible - 2022-05-19	A0 - Fix ASAP - 2022-05-19	

Safety inspection (skydds rond) in room 7134

Type of room: Lab | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x3 - Insufficient storage - 2021-03-30	A500 - More storage needed - 2021-05-31 A501 - More shelves needed - 2021-05-31	Non specific 2022-11-30 - some issues moved to 7134S

Safety inspection (skydds rond) in room 7134S

Type of room: Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x110 - Flammables incorectly stored - 2022-11-30 x110: flammables in fume hood x905 - Missing pictograms on fire proof cabinet - 2022-11-30		

Safety inspection (skydds rond) in room 7138

Type of room: Lab | Previous issues fixed: **Yes** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-05-17 x101/x103: Flammables on bench		

Safety inspection (skydds rond) in room 7138S

Type of room: Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x103 - Flammable in non-fire proof cabinet - 2022-11-23 x103/x800: flammable waste in ventilated cupboard under fume hood - fixed - moved to fire proof cabinet x800 - Waste handling/storing not correct - 2022-11-23 x103/x800: flammable waste in ventilated cupboard under fume hood - fixed - moved to fire proof cabinet		

Safety inspection (skydds rond) in room 7152

Type of room: Cell Lab Air Lock | Previous issues fixed: **Yes** | [update this room](#)

Issues w comments	Actions w comments	Comments
x902 - Missing warning/information signs/pictograms - 2022-11-30 x902: Pictograms on fridge x902: Waste not labeled correctly - was fixed x902: waste w/o pictograms - fixed x903 - Incorrect warning signs/pictograms - 2022-11-30		

Safety inspection (skydds rond) in room 7155

Type of room: Cell Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-11-23 x101: ethanol sq bottles		

Safety inspection (skydds rond) in room 7156

Type of room: Lab Equipment Room | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x340 - Electrical risks - 2022-11-23 x340: many PCR on same fuse		

Safety inspection (skyddsron) in room 7160

Type of room: Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x907 - Missing pictograms on fridge/freezer - 2022-11-30	A402 - Label it/them with correct hazard pictograms - 2022-11-23 A502 - Floor shelves needed - 2021-03-30	Non specific <u>2021-03-30</u> - Eye shower log missing

Safety inspection (skyddsron) in room 7305E1

Type of room: Niche for electricity in LCI lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x10 - Box(es) on the floor - 2022-11-25 x10: boxes w extension cords on the floor	A211 - Move to service storage - 2022-11-25	

Safety inspection (skyddsron) in room 7313

Type of room: Lab Office | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x108 - Hand disinfectant - 2022-11-29		

Safety inspection (skyddsron) in room 7320

Type of room: Lab Office | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x134 - Electric kettle not allowed - may blow fuses - 2022-11-29 x134/A200: Use outlet by the coffee machines, or remove x135 - Microwave - may blow fuses - 2022-11-29	A200 - Move to other location - 2022-11-29 x134/A200: Use outlet by the coffee machines, or remove	

Safety inspection (skyddsron) in room 7331

Type of room: Lab | Previous issues fixed: **Yes** | [update this room](#)

Issues w comments	Actions w comments	Comments
x3 - Insufficient storage - 2021-12-13	A502 - Floor shelves needed - 2022-05-17	Non specific <u>2021-12-13</u> - SICOF shelves still needed

Safety inspection (skyddsron) in room 7333

Type of room: SICOF Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x3 - Insufficient storage - 2022-05-19	A502 - Floor shelves needed - 2021-12-13	Non specific <u>2022-05-19</u> - Alarm siren is audible

Safety inspection (skyddsron) in room 7336

Type of room: not existing | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-05-17 x101: Flammables on bench x103 - Flammable in non-fire proof cabinet - 2022-05-17	A200 - Move to other location - 2022-05-17	

Safety inspection (skyddsron) in room 7341S

Type of room: Lab | Previous issues fixed: **Yes** | [update this room](#)

Issues w comments	Actions w comments	Comments
x1 - Untidy/messy - 2022-11-25	A2 - Clean up - 2022-11-25	

Safety inspection (skyddsron) in room 7343

Type of room: not existing | Previous issues fixed: **Not checked** | [update this room](#)

Issues w comments	Actions w comments	Comments
x3 - Insufficient storage - 2021-05-31	A502 - Floor shelves needed - 2020-11-04	Non specific

Safety inspection (skyddsron) in room 7345N

Type of room: Lab | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x1 - Untidy/messy - 2022-11-25 x202 - Improper storage in fumehood - 2022-11-25 x3 - Insufficient storage - 2022-11-25 x902 - Missing warning/information signs/pictograms - 2022-11-25	A102 - Shelves - 80 needed - 2022-11-25 A102: shelf above the fridge A400 - Use proper Signs and/or labels - 2021-12-20	

Safety inspection (skyddsron) in room 7345S

Type of room: Lab | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-11-23 x101: ethanol bottle on bench		

Safety inspection (skyddsron) in room 7349

Type of room: Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-05-17 x101/x103: Flammables on bench x8 - Many cardboard/styrofoam boxes in the room - 2021-03-30		Non specific <u>2021-03-30</u> - Too many yellow bins <u>2021-03-30</u> - Heater wo timer <u>2021-03-30</u> - Chem cupboards wo pictograms

Safety inspection (skyddsron) in room 7349N

Type of room: Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x15 - Boxes/storage on top of fridge/freezers - 2022-11-25 x15: Styrofoam dropped down behind fridge x3 - Insufficient storage - 2022-11-25 x902 - Missing warning/information signs/pictograms - 2022-11-25 x902: pictograms on fridge needed	A102 - Shelves - 80 needed - 2022-11-25 A102: shelf above fridge	

Safety inspection (skyddsron) in room 7349S

Type of room: Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x801 - Improper storage of hazardous waste - 2022-11-25 x801: Phenolic waste in jerrican on floor under fumehood - no pictogram		

Safety inspection (skyddsron) in room 7353

Type of room: Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x7 - Card board boxes in cold room - 2022-11-25	A208 - Move to plastic boxes - 2022-11-25	

Safety inspection (skyddsron) in room 7362

Type of room: LCI Lab | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
1003 - Fire risks - Other - 2021-03-30 x602 - Eye shower - 2022-11-25 x602: eye shower not flushed by fire monitor x673 - Evacuation siren/alarm malfunction - 2022-05-19 x673: Siren not activated when building evacuation is activated (maybe same problem as in 7130) and corridor siren is not audible x674 - Evacuation alarm not audible - 2022-05-19	A0 - Fix ASAP - 2022-05-19 A300 - Fix, repair, or install needed - 2021-06-01	Non specific 2021-03-30 - Two more doors need checking

Safety inspection (skyddsron) in room 7372

Type of room: Lab Equipment Room | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x3 - Insufficient storage - 2021-05-31	A502 - Floor shelves needed - 2020-11-04	Non specific

Safety inspection (skyddsron) in room 7376

Type of room: Lab Equipment Room | Previous issues fixed: **Yes** | [update this room](#)

Issues w comments	Actions w comments	Comments
x3 - Insufficient storage - 2022-11-25 x3: fire proof cabinet used for storage of non flammable objects	A502 - Floor shelves needed - 2021-03-30	

Safety inspection (skyddsron) in room 7378

Type of room: Lab Equipment Room | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x11 - Heavy objects stored high - 2022-11-25 x11: glassware stored on top of wallcupboard x3 - Insufficient storage - 2022-11-25	A502 - Floor shelves needed - 2022-11-25	

Safety inspection (skyddsron) in room 7380

Type of room: Lab Equipment Room | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x3 - Insufficient storage - 2021-12-17	A502 - Floor shelves needed - 2021-12-13	Non specific 2021-12-13 - Lots of floor shelves needed

Safety inspection (skyddsron) in room 7383

Type of room: Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x109 - Surface disinfectant - 2022-11-29		

Safety inspection (skyddsron) in room 7510

Type of room: Lab Office | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-11-23 x101: surface disinfectant in the office!		

Safety inspection (skyddsron) in room 7531N

Type of room: Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-11-25 x101: ethanol		

Safety inspection (skyddsron) in room 7531S

Type of room: Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-11-25 x101: ethanol		

Safety inspection (skyddsron) in room 7535

Type of room: Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments

x101 - To much flammable in the lab - 2022-11-25
X101/x102: flammable on benches, in LAF-bench and in non fire proof cupboard
x103 - Flammable in non-fire proof cabinet - 2022-11-25
x230 - Hazardous, infectious material stored/handled incorrectly - 2022-11-25
x230: LAF-bench marked BSL2 - According to KI rules all BSL2 material must be handled in a BSL2 lab

Safety inspection (skyddsron) in room 7552

Type of room: Lab Equipment Room | Previous issues fixed: **Yes** | [update this room](#)

Issues w comments	Actions w comments	Comments
x210 - Chemicals stored incorrectly - 2022-11-25 x210: SOK old chemicals - dispose(?) x3 - Insufficient storage - 2021-12-17	A103 - Shelves - 80 deep needed - 2021-12-13	

Safety inspection (skyddsron) in room 7554

Type of room: Lab Equipment Room | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x11 - Heavy objects stored high - 2022-11-25 x11: heavy object on top shelf x4 - Many things on the floor/in the room - 2022-11-25 x4: many empty yellow bins (fetch new when needed, do not store them in the lab)	A201 - Move or remove - 2021-12-20	Non specific 2021-12-20 - Move to recycling room. Update routine so to this regularly

Safety inspection (skyddsron) in room 7555

Type of room: Dark Room | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x3 - Insufficient storage - 2021-05-31	A502 - Floor shelves needed - 2021-03-30	

Safety inspection (skyddsron) in room 7556

Type of room: Cell Lab Air Lock | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
1005 - Equipment - Other - 2022-11-25 1005: Shoe shelves needed x602 - Eye shower - 2022-11-25 x602: eye shower not flushed by fire monitor x8 - Many cardboard/styrofoam boxes in the room - 2022-11-25		

Safety inspection (skyddsron) in room 7593S

Type of room: Lab | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x15 - Boxes/storage on top of fridge/freezers - 2022-11-23 x15: Boxes dropped down behind fridge		

Safety inspection (skyddsron) in room 7631

Type of room: Lab Equipment Room | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-11-23 x101: several ethanol sq bottles		

Safety inspection (skyddsron) in room 7634

Type of room: Chemical Storage | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x104 - Gas cartridges/tanks NOT stored in fire proof cabinet - 2021-12-13 x210 - Chemicals stored incorrectly - 2021-12-13 x601 - Emergency shower - 2022-11-25 x601: Showers not flushed by fire monitors x902 - Missing warning/information signs/pictograms - 2021-12-13	A400 - Use proper Signs and/or labels - 2021-06-15	Non specific 2021-12-13 - Empty gas cartridges 2021-12-13 - Old KDW chemicals 2021-12-13 - SOK chemicals to be discarded

Safety inspection (skyddsron) in room 7635

Type of room: Lab Equipment Room | Previous issues fixed: **Yes** | [update this room](#)

Issues w comments	Actions w comments	Comments
x901 - Missing responsible person sign - 2022-11-23		

Safety inspection (skyddsron) in room 7636

Type of room: Lab Equipment Room | Previous issues fixed: **Yes** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-11-23		

Safety inspection (skyddsron) in room 7704

Type of room: RWC | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x670 - Alarm button - 2022-11-23 x670: We do not know if the alarm button is correctly connecte and programmed		

Safety inspection (skyddsron) in room 7819

Type of room: Office | Previous issues fixed: **Not checked** | [update this room](#)

Issues w comments	Actions w comments	Comments
x132 - Electric heater - may blow fuses - 2021-05-31	A220 - Remove - 2021-05-31	Non specific 2021-05-31 - Remove heater when the building heating system is fixed

Safety inspection (skyddsron) in room 7821

Type of room: Office | Previous issues fixed: **Not checked** | [update this room](#)

Issues w comments	Actions w comments	Comments
x132 - Electric heater - may blow fuses - 2021-05-31	A220 - Remove - 2021-05-31	Non specific <u>2021-05-31 - Remove heater when the building heating system is fixed</u>

Safety inspection (skydds rond) in room 7830

Type of room: Office | Previous issues fixed: **Not checked** | [update this room](#)

Issues w comments	Actions w comments	Comments
x707 - General lighting - 2021-03-30	A340 - Order the repair/install/fix - 2021-06-15	Non specific <u>2021-03-30 - Switches off when people are in the room</u>

Safety inspection (skydds rond) in room 7840

Type of room: Office | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x674 - Evacuation alarm not audible - 2022-05-30 x674: Alarm is not audible if door is closed		

Safety inspection (skydds rond) in room 8020

Type of room: Office | Previous issues fixed: **Not checked** | [update this room](#)

Issues w comments	Actions w comments	Comments
x132 - Electric heater - may blow fuses - 2021-12-14	A201 - Move or remove - 2021-12-17	

Safety inspection (skydds rond) in room 8021

Type of room: Office | Previous issues fixed: **Not checked** | [update this room](#)

Issues w comments	Actions w comments	Comments
x132 - Electric heater - may blow fuses - 2021-12-14	A201 - Move or remove - 2021-12-20	

Safety inspection (skydds rond) in room 8032

Type of room: Lab Equipment Room | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-11-21 x101: EtOH - Store in fire proof cabinet when the room is not in use x902 - Missing warning/information signs/pictograms - 2022-11-21 x902/A400: use sign for sonicator	A200 - Move to other location - 2022-11-21 A400 - Use proper Signs and/or labels - 2021-06-15 x902/A400: use sign for sonicator	

Safety inspection (skydds rond) in room 8033

Type of room: Lab Equipment Room | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-11-21 x101: EtOH - Store in fire proof cabinet when the room is not in use	A200 - Move to other location - 2022-11-21	

Safety inspection (skydds rond) in room 8034

Type of room: Storage | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
1003 - Fire risks - Other - 2022-11-21 1003: Boxes and shelves moved and removed	A201 - Move or remove - 2021-12-20	Non specific <u>2021-12-20 - At least 30 cm from sprinkler to any stored material</u>

Safety inspection (skydds rond) in room 8036

Type of room: Lab Equipment Room | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-11-21 x101: Many EtOH bottles x101: Flammables on bench x3 - Insufficient storage - 2021-12-13 x902 - Missing warning/information signs/pictograms - 2022-11-21 x902: Radioactive sign on equipment needed	A502 - Floor shelves needed - 2022-11-21	Non specific <u>2021-12-13 - sq bootles w ethanol on bench</u>

Safety inspection (skydds rond) in room 8039

Type of room: Chemical Storage | Previous issues fixed: **Not checked** | [update this room](#)

Issues w comments	Actions w comments	Comments
x103 - Flammable in non-fire proof cabinet - 2021-12-13	A200 - Move to other location - 2021-12-20	Non specific <u>2021-12-13 - JJO Move to fireproof, move non-flammable from fireproof cabinet</u>

Safety inspection (skydds rond) in room 8108

Type of room: Lab Corridor | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x602 - Eye shower - 2022-11-21 x602: Too low pressure in eye shower x602: Too low pressure in eye shower x670 - Alarm button - 2022-11-21 x670: spill button malfunction x675 - Evacuation sign missing/malfunctioning - 2022-12-05 x675: No evac sign at N end, towards corridor 8101	A998 - Request for repair/fix has been sent - 2022-11-29 A998: eye shower repair has been ordered	

Safety inspection (skydds rond) in room 8121

Type of room: Silent Room | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x1 - Untidy/messy - 2021-12-14	A3 - Clean by user - 2021-12-14	

Safety inspection (skydds rond) in room 8123

Type of room: Lab Office | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments

x106 - Evacuation routes (partly) blocked - 2022-11-21
x106: unstable coat hanger, should be fixed
x106/A221: cloth rack unsecured next to corridor / door (may block if falling when evacuating)

A221 - Remove or install - 2022-05-17
x106/A221: cloth rack unsecured next to corridor / door (may block if falling when evacuating)

Safety inspection (skyddsron) in room 8130

Type of room: Lab | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-11-21 x101: Ethanol on bench x101: Flammables on bench	A200 - Move to other location - 2021-06-15 A220 - Remove - 2021-06-15	Non specific 2021-06-15 - Flammables should not be stored in non-fireproof cupboards, so, a sign for storing flammable should NOT be on those cupboards: Remove id/them 2021-06-15 - Heat blocks and other heating equipment should have timers: Install

Safety inspection (skyddsron) in room 8134

Type of room: Lab | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-12-02 x101: Several ethanol sq. bottles		

Safety inspection (skyddsron) in room 8138

Type of room: Lab | Previous issues fixed: **Yes** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-11-21 x101: Ethanol sq. bottles		

Safety inspection (skyddsron) in room 8138N

Type of room: Lab | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x3 - Insufficient storage - 2021-12-17	A501 - More shelves needed - 2021-12-13	Non specific 2022-12-02 - Cleared from radioactive contamination - no more rad work here! 2021-12-13 - Radioactive work approved by Sofia

Safety inspection (skyddsron) in room 8150

Type of room: Cell Lab | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2021-12-13 x101: surface disinfectant	A206 - Move to fireproof cupboard - 2021-12-20	

Safety inspection (skyddsron) in room 8152

Type of room: Cell Lab Air Lock | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-05-16 x101: Flammables on bench	A300 - Fix, repair, or install needed - 2021-06-15	Non specific 2021-12-13 - EtOH on bench

Safety inspection (skyddsron) in room 8155

Type of room: Cell Lab | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-11-21 x107 - Spray bottle with flammables - 2022-11-21	A200 - Move to other location - 2021-06-01	Non specific 2021-12-13 - EtOH on bench

Safety inspection (skyddsron) in room 8156

Type of room: Cold Room | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x7 - Card board boxes in cold room - 2022-11-21 x903 - Incorrect warning signs/pictograms - 2022-11-21	A208 - Move to plastic boxes - 2022-11-21	Non specific 2022-11-21 - x903. flammable pictogram on the door. The cold room is not a proper store for flammable material

Safety inspection (skyddsron) in room 8158

Type of room: Lab Equipment Room | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x3 - Insufficient storage - 2021-12-17	A6 - Floor shelf 80 needed - 2021-03-29	

Safety inspection (skyddsron) in room 8160

Type of room: Lab Equipment Room | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x706 - Disturbing noise - 2021-12-20	A300 - Fix, repair, or install needed - 2021-12-20	Non specific 2021-12-20 - Improve AC in the room or remove some heat generated equipment. Then the door can be closed

Safety inspection (skyddsron) in room 8308

Type of room: Lab Corridor | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x660 - Low oxygen alarm - 2022-09-15 x902 - Missing warning/information signs/pictograms - 2022-09-15	A998 - Request for repair/fix has been sent - 2021-06-15	Non specific 2022-09-15 - The NMR in 8383 is down and has no liquid helium or nitrogen. No immediate need for a low oxygen alarm in the corridor 2022-09-15 - justerat vattentrycket för ögonuschen 2021-12-17 - Low ox alarm ot yet installed

Safety inspection (skyddsron) in room 8331

Type of room: Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
1009 - Sign & Labels - Other - 2022-11-21 x902 - Missing warning/information signs/pictograms - 2022-11-29 x902: Permanently closed door should have a sign stating that it is no entry/exit	A404 - Put up a sign - 2022-11-21	

Safety inspection (skyddsron) in room 8341

Type of room: Org. Chem. Analysis 1 | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x902 - Missing warning/information signs/pictograms - 2021-06-15	A400 - Use proper Signs and/or labels - 2021-06-15	Non specific 2022-12-02 - Sign needed that the warning for low O2 is not currently in use 2021-06-15 - Chemical signs needed on cupboard

Safety inspection (skyddsron) in room 8345

Type of room: Org. Chem. RNA/DNA Lab | Previous issues fixed: **Not checked** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-05-16 x101: Flammables on bench x103 - Flammable in non-fire proof cabinet - 2022-05-16 x902 - Missing warning/information signs/pictograms - 2022-05-16	A200 - Move to other location - 2022-05-16 A502 - Floor shelves needed - 2022-05-16	Non specific 2022-05-16 - flammables also placed next to sink

Safety inspection (skyddsron) in room 8349

Type of room: Org. Chem. Lab | Previous issues fixed: **Not checked** | [update this room](#)

Issues w comments	Actions w comments	Comments
1003 - Fire risks - Other - 2021-03-29 1003: Flammables, acetone and ethanol, at sink without container x202 - Improper storage in fumehood - 2021-12-13	A200 - Move to other location - 2021-06-01 A204 - Move to correct cupboard - 2021-06-01	Non specific 2021-12-13 - messy fumehoods 2021-06-01 - Put squeeze bottles at the sink in an other container 2021-03-29 - Reentered issues due to a bug

Safety inspection (skyddsron) in room 8351

Type of room: Org. Chem. Rotavap Lab | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x640 - Insufficient ventilation - 2021-12-20	A300 - Fix, repair, or install needed - 2021-12-20	Non specific 2021-12-20 - If the capacity of the airflow can not be increased, it may be needed to cover part of the fume bench and only use the part with proper ventilation

Safety inspection (skyddsron) in room 8353

Type of room: Org. Chem. Stink Lab | Previous issues fixed: **Not checked** | [update this room](#)

Issues w comments	Actions w comments	Comments
x601 - Emergency shower - 2021-06-15 x602 - Eye shower - 2021-06-15	A200 - Move to other location - 2021-06-15	Non specific 2021-06-15 - Move blocking material to other location. 2021-06-15 - Move filled waste containers to waste room(s) before filling too much

Safety inspection (skyddsron) in room 8354

Type of room: Org. Chem. Chem Storage | Previous issues fixed: **Not checked** | [update this room](#)

Issues w comments	Actions w comments	Comments
x15 - Boxes/storage on top of fridge/freezers - 2021-06-15	A200 - Move to other location - 2021-06-15	

Safety inspection (skyddsron) in room 8360

Type of room: Recycling room | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
1009 - Sign & Labels - Other - 2022-11-21		

Safety inspection (skyddsron) in room 8374

Type of room: Lab Equipment Room | Previous issues fixed: **Not checked** | [update this room](#)

Issues w comments	Actions w comments	Comments
x8 - Many cardboard/styrofoam boxes in the room - 2022-11-21		Non specific 2022-12-08 - Virkon jerrican w incorrect label fixed

Safety inspection (skyddsron) in room 8375

Type of room: Lab Equipment Room | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x160 - Labcoat hanger - 2022-12-02 x160: Lab coat hangers needed x320 - Handwashing facilities missing - 2022-11-21 x320: handwashing missing x902 - Missing warning/information signs/pictograms - 2022-11-21 x902: BSL2 sign needed	A340 - Order the repair/install/fix - 2022-12-02 A413 - Sign 'BIOLOGISK RISK' needed - 2022-11-21	

Safety inspection (skyddsron) in room 8378

Type of room: Isotope Lab | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-11-21 x101: Ethanol surface disinfectant on bench x3 - Insufficient storage - 2021-12-17	A502 - Floor shelves needed - 2022-11-21	

Safety inspection (skyddsron) in room 8382

Type of room: Org. Chem. UV Lab | Previous issues fixed: **Not checked** | [update this room](#)

Issues w comments	Actions w comments	Comments
-------------------	--------------------	----------

1004 - Fire & Safety equipment - Other - 2021-05-31
x660 - Low oxygen alarm - 2021-05-31

A998 - Request for repair/fix has been sent - 2021-05-31

Non specific

2022-12-02 - Org.Chem is moving to LabMed. This room is currently storing equipment to be discarded or moved. Not used as a lab.

2021-05-31 - Low O2 alarm in corridor 8308 will be installed

2021-05-31 - Put squeeze bottle in outer container (this is a separate fire cell so the total amount of flammables are well below the limit)

Safety inspection (skyddsron) in room 8554

Type of room: Cold Room | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x7 - Card board boxes in cold room - 2022-11-21 x7: Still cardboard boxes and other stuff that should be removed x7: Mold may grow on card bord boxes in cold room. x8 - Many cardboard/styrofoam boxes in the room - 2021-06-15	A208 - Move to plastic boxes - 2021-06-15	

Safety inspection (skyddsron) in room 8557

Type of room: Cell Lab | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-11-21 x101: Ethanol on bench when lab not in use		

Safety inspection (skyddsron) in room 8560

Type of room: Cell Lab | Previous issues fixed: **Yes** | [update this room](#)

Issues w comments	Actions w comments	Comments
x8 - Many cardboard/styrofoam boxes in the room - 2022-11-21 x8: styrofoam boxes	A220 - Remove - 2022-11-21	

Safety inspection (skyddsron) in room 8606

Type of room: Office Corridor | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x351 - Malfunctioning door - 2022-05-19 x351: Fire door to 8605 did not close when evacuation alarm was activated. It did close when button was pressed		

Safety inspection (skyddsron) in room 8620

Type of room: Service Group Office | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x101 - To much flammable in the lab - 2022-11-21 x101: Ethanol bottles		

Safety inspection (skyddsron) in room 8634

Type of room: Chemical Storage | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x210 - Chemicals stored incorrectly - 2022-11-21 x210: Old chemicals that should be moved or discarded x230 - Hazardous, infectious material stored/handled incorrectly - 2022-11-21 x230: Old samples in Falcon tubes x902 - Missing warning/information signs/pictograms - 2021-03-31 x902: warning pictograms outside door		

Safety inspection (skyddsron) in room 8637

Type of room: Lab Equipment Room | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x4 - Many things on the floor/in the room - 2022-11-25 x4: Some stuff that should be moved		

Safety inspection (skyddsron) in room 8813

Type of room: Office | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x8 - Many cardboard/styrofoam boxes in the room - 2022-11-21 x8: replace the styrofoam boxes with more less flammable boxes	A200 - Move to other location - 2021-06-15	Non specific 2021-12-13 - Still there

Safety inspection (skyddsron) in room 8816

Type of room: Office | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x132 - Electric heater - may blow fuses - 2021-05-31 x132: Remove heater when the building heating system is fixed	A220 - Remove - 2021-05-31	

Safety inspection (skyddsron) in room 8817

Type of room: Office | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x132 - Electric heater - may blow fuses - 2021-05-31 x132/A220: Remove heater when the building heating system is fixed	A220 - Remove - 2021-05-31 x132/A220: Remove heater when the building heating system is fixed	

Safety inspection (skyddsron) in room 8820

Type of room: Office | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x12 - Moving boxes - 2022-11-21		

Safety inspection (skyddsron) in room 8835

Type of room: Cold Room -20C | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
1001 - General order - Other - 2022-11-21 x210 - Chemicals stored incorrectly - 2021-12-13 x7 - Card board boxes in cold room - 2022-11-21 x7: SOK boxes on floor x7: SOK boxes on floor	A201 - Move or remove - 2021-12-20	

Safety inspection (skydds rond) in room 8836

Type of room: Cold Room +4C | Previous issues fixed: **Yes** | [update this room](#)

Issues w comments	Actions w comments	Comments
x210 - Chemicals stored incorrectly - 2021-12-13 x230 - Hazardous, infectious material stored/handled incorrectly - 2022-11-21 x230: Samples in Falcon tubes	A201 - Move or remove - 2021-12-20 A202 - Unpack - 2021-12-20	

Safety inspection (skydds rond) in room 8837

Type of room: Cold Room +4C | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
x210 - Chemicals stored incorrectly - 2021-12-13	A200 - Move to other location - 2021-12-20 A201 - Move or remove - 2021-12-20 A201: SOK boxes on floor	

Safety inspection (skydds rond) in room 8839

Type of room: BioNut Server Room | Previous issues fixed: **Not applicable** | [update this room](#)

Issues w comments	Actions w comments	Comments
x674 - Evacuation alarm not audible - 2022-12-02	A0 - Fix ASAP - 2022-12-02 A340 - Order the repair/install/fix - 2022-12-02	Non specific <u>2022-12-02 - The buiding fire alarm is not audible</u>

Safety inspection (skydds rond) in room 8846

Type of room: Locker room | Previous issues fixed: **No** | [update this room](#)

Issues w comments	Actions w comments	Comments
1002 - Indoor climate - Other - 2020-11-04 1002: Hangers for wet towels	A330 - Install - 2020-11-04 A330: väggfasta krokar behövs i herrarnas omklädningsrum	